# 

_	_
ш	
ш	
ш	ш

	BST-1041
	4200+ PVC0000
	0.9-5.5
N.W.	122□/ PC
	<u>+1010_/</u>
G.W.	20700/0

## 

 $I \square C \square \square \square \square \square \square \square \square$ 

\_\_\_\_D.I.Y\_\_\_







### **User manual**



## Warning

This model is not insulated tools. Please use it when power off.



### Attention

- To protect user safe, please use protective glasses.
- As the cut material will fly out, make sure no one beside you and no easy damaged things beside you, then begin working.
- This product is not a dedicated pressure equipment.
- When stored, please assure the blade at the closed state and can not be touched by children.
- Do not let the plier tip rub something.
- Please do not directly touch the blade part with hand.
- Do not use in cutting hard materials and steel wire, etc.
- Do not use the pliers above its cutting capability and coarse wire.

## PRODUCT PHOTOGRAPH







### WEIGHT:147G



**FRONT** 

BACK