
BEST________



PRODUCT DISPLAY



PRODUCT SIZE



PRODUCT FEATURES







Why need rosin

As the metal surface with air contact will produce a layer of oxide film, the higher the temperature, the more oxidation of this layer of oxide film to prevent the liquid solder on the metal lubrication, like the glass stained with oil will make the water can not wet the same. Welding machine is used to remove the oxide film of a special material, also known as flux - rosin.





