

Presupuesto

Pen Type Gas Soldering Iron

1. Portable, usar en cualquier lugar en cualquier momento
2. Nueva energía: butano puro

BST-100 Pen Type Soldador de gas

Descripción del producto

Instrucción

1. Rellene con gas después de confirmar que el interruptor se ha apagado.
2. Rellene con gas como imagen 1. Vaya el tanque de gasolina al orificio de llenado y presione para llenar.
3. Tarda unos 10 segundos en completar el llenado. Espere varios minutos para que el gas esté estable antes de usar.
4. Presione ligeramente la entrada de aire si hay ruido ZIZI después del llenado.
5. Encienda el interruptor hasta que escuche ruido ZIZI como en la imagen 2.
6. Mueva el anillo de ignición hacia adelante como la imagen 3.
7. Incendia la punta con un encendedor como en la imagen 4
8. La llama se vuelve más grande cuando se mueve a '+', más pequeña cuando a '-'.
9. Empiece a usar cuando la llama desaparece y la punta se vuelve roja. La llama no debe ser demasiado grande para prolongar la vida útil.
10. La longitud de la llama es de aproximadamente 12 mm a 15 mm.

Importante: Lea las instrucciones antes de usar y siga la secuencia de operación, para evitar el peligro de una operación incorrecta.

PRODUCT DISPLAY



PRODUCT SIZE



PRODUCT FEATURES



Warning

- ▶ Please read the instruction before using and follow the operation sequence, so as to avoid the danger for improper operation .

Instruction

- ▶ 1.Fill with gas after confirming the switch has been turned off.
- ▶ 2.Fill with gas as picture 1.Lead the gas tank to the filling hole and press to fill.
- ▶ 3.It takes about 10 seconds to complete the filling. Wait several minutes to let the gas be steady before use.
- ▶ 4.Please press the air intake lightly if there is ZIZI noise after filling.
- ▶ 5.Turn on the switch until you hear ZIZI noise as picture 2.
- ▶ 6.Move the flameout ring forward as picture 3.
- ▶ 7.Fire the tip with lighter as picture 4
- ▶ 8.The flame become larger when move to '+',smaller when to '- '.
- ▶ 9.Begin to use when the flame disappears and the tip turns red.
The flame should not be too large so as to prolong the service life.
- ▶ 10.The length of the flame is about 12 mm to 15 mm.



picture 1



picture 2



picture 3



picture 4

PRODUCT PHOTOGRAPH





PRODUCT PACKAGING

WEIGHT:72G



FRONT



BACK