

Features

□ □□ □ □□ □□ □□ □□ □□□□ 2 □□ □□□ □□ □□ □□□□ □□□□ 12 □□ □□□□□ □□□□□.

□□□ □□□ □□ □□□□ p.c.□□□□□ □□ □□ □□ ...!□□ 185mm □□ 75mm □□.□□ □□□ □□ □□ □□ □□□ □□□ □□.

Specification

SA-10 6 □□□ □□ □□□

1. □□□ : □□ □□ □□
2. □□□□□ : □□□ □□ □ □ □□ □□□□□□
3. □□□ : PCB □□□ □□□□ □ □□□□□
4. □□ : □□ □ □ □□
5. □□ : □□ 22SWG□□ □□□ □□□.□□ □ □□ □
6. □□□□ : □□ □ □□ □

产品描述



名称: 6件套助焊工具

型号: BST-SA-10

品牌: 倍思特

磁性: 不带磁性

尺寸: 185mm

重量: 85g

特点1: 针对机板修补、组立、拆除元件、研磨、清洁，除锡而设计


特点2: 将焊接维修时所常用的压、钻、撬、戳、切、刮、钩、拉、顶、刷...等12种需求集中在6支辅助工具上

特点3: 用于安装和维修电路板，广泛应用于印刷电路板（PCB）的焊接组装和维修工作

产品尺寸




BST-SA-10: 刷子




焊锡前清除焊锡部位的粉尘和残留物
清除焊锡时产生的锡球，去除锈斑

BST-SA-10: 叉




固定或调整元件的引脚和连接线
及电阻、电容等元件脚成型用

BST-SA-10: 刀




可切割印刷线路板上的敷铜连接线，印刷电路回路修正，切断，去锈时使用




去残留的焊锡和助焊剂
清除焊盘和金手指上的化层，刮锈蚀，氧化层等用

BST-SA-10: 勾




平面集成电路元件，
拆取时使用，电烙铁
边溶解边拆除




拆除电阻元件时使用，
电烙铁边溶解边拆除

BST-SA-10: 铰刀



印刷电路板孔扩大及焊锡堵塞孔的修复用

BST-SA-10: 压头



小型电子元件压紧，定位后锡焊
圆形元件，平时元件对应压头